

Chula Vista Light Rail Corridor Improvements

Project Study Report

SANDAG / City of Chula Vista

APPENDIX B: Site Photos

Chula Vista Light Rail Corridor Improvements

Project Study Report

SANDAG / City of Chula Vista



E Street Looking North

Chula Vista Light Rail Corridor Improvements

Project Study Report

SANDAG / City of Chula Vista



E Street Looking South



E Street View Corridor

Chula Vista Light Rail Corridor Improvements

Project Study Report

SANDAG / City of Chula Vista



E Street Visitor Center in Station Parking Lot



E Street Bus Turnouts at Station

Chula Vista Light Rail Corridor Improvements

Project Study Report

SANDAG / City of Chula Vista



H Street Looking North

Chula Vista Light Rail Corridor Improvements

Project Study Report

SANDAG / City of Chula Vista



H Street Looking South



H Street Concrete Lined Ditch Looking North

Chula Vista Light Rail Corridor Improvements

Project Study Report

SANDAG / City of Chula Vista



H Street Station



H Street Bus Turnouts

Chula Vista Light Rail Corridor Improvements

Project Study Report

SANDAG / City of Chula Vista



Palomar Street Looking North

Chula Vista Light Rail Corridor Improvements

Project Study Report

SANDAG / City of Chula Vista



Palomar Street Looking South



Palomar Street Intersection with Industrial Blvd.

Chula Vista Light Rail Corridor Improvements

Project Study Report

SANDAG / City of Chula Vista



Palomar Street Bus Turnouts



Palomar Street SDG&E Poles